


# PLASMA CUTTING TORCHES

## CBR50 Plasma Torch & Spares

Air Cooled 50 Amp



Torch Model	
Description	Part Number
CBR50 PLASMA TORCH 4m	CBR50-40/60-MI6x1.5

Spare Parts		
No	WGA Part No.	Description
1	SG5014R	Plasma Handle
2	SC2516R	Plasma safety Trigger
3	CBR1352	CBR50 70 Torch Head
4	SC5019-40/60-M16X1.5	Cable Assembly complete
5	1521-HF	Electrode Hafnium
6	SC1510	Swirl Ring
7	1304	Cutting Tip
8	5.710.121	Retaining Cap
9	SCSP1	Screw Pack
10	1518-HF	Electrode Hafnium Extended
11	1370	Cutting Tip Extended
12	1394S-50	Shield Cap Hand